

**From:** [Nancy Jones](#)  
**To:** [Willie Kelley](#); [Steve Vargo](#); [Alan Annicella](#)  
**Cc:** [R6\\_DWH\\_Info@epamail.epa.gov](#)  
**Subject:** Fw: H2S Treatment  
**Date:** 07/11/2010 07:36 AM  
**Importance:** High  
**Attachments:** [sx9272.pdf](#)

---

See below - any concerns?

-----

Sent by EPA Wireless E-Mail Services

---

**From:** "Rice, Cecilia (BP MC252)" [Cecilia.Rice1@bp.com]  
**Sent:** 07/11/2010 07:17 AM EST  
**To:** Nancy Jones; <phyllis.luke@la.gov>  
**Cc:** "Crame, Leonard (BP MC252)" <LEONARD.CRAME@bp.com>; "Green, Theodore" <tgreen@croworld.com>; <Ricky.Belk@heritage-enviro.com>  
**Subject:** FW: H2S Treatment

Nancy and Phyllis,

BP decided they need to change the chemical to convert the H2S in the barges. Here is the new MSDS. Please let me know if there are any issues with this material.

Thanks,  
C.C. Rice

---

**From:** Belk, Ricky [mailto:Ricky.Belk@heritage-enviro.com]  
**Sent:** Sunday, July 11, 2010 7:00 AM  
**To:** Rice, Cecilia (BP MC252)  
**Subject:** FW: H2S Treatment

**Ricky Belk | Operations Manager**  
Heritage Environmental Services, LLC | Tulsa Service Center  
Office-918.627-2671 | Cell-918.629.1324 | Fax-918.627.2108  
email: [ricky.belk@heritage-enviro.com](mailto:ricky.belk@heritage-enviro.com) web site: [www.heritage-enviro.com](http://www.heritage-enviro.com)